# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 01/09/2020

## REPORT ON GROUND WATER INVESTIGATION

1

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | w no 12 AGB Layout sri R Manjunath house |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 20-30 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1000-1500 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS

GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾ[illegible] ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು [illegible] ಪಾಲಿಕೆ
[illegible], ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 01/09/2020

## REPORT ON GROUND WATER INVESTIGATION

2

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no, 12, AGB Lyt, 1st cross, shettyhalli |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 330-350 rmt |
| 06. Approximate Casing Pipe | 20-30 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1000-1500 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

3

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no12, 4th cross, shettyhalli, AGB Lyt |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 360-370 rmt |
| 06. Approximate Casing Pipe | 20-30 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1500-2000 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

4

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no 12 Vinayaka nagara, mayura bekary road, Chikkabanawara |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 320-330 rmt |
| 06. Approximate Casing Pipe | 20-30 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1500-2000 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

5

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no 12, Vinayaka badavane, shettyhalli, |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 30-40 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1500-2000 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರಾಜಾಜಿನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

6

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no12, vinayaka badavane. RR collage road near |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 310-330 rmt |
| 06. Approximate Casing Pipe | 30-40 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1500-2000 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ಗಂಗಾಧರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

7

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no12 babanna layout 3rd cross Hatti Lakamma temple road mallasandra |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 30-40 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1000-1500 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

8

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no12 B Hanumathaiah layout 4 th cross chikka sandra |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 20-40 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1000-1500 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

9

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | W no12 marrison layout |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 30-50 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1000-1500 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

# RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 1/9/2020

## REPORT ON GROUND WATER INVESTIGATION

10

| | |
|---|---|
| 01. Name of the Party | **Executive Engineer, BBMP, T.Dasarahalli Division.** |
| 02. Location of land/Site | Ward no-12 Shettyhalli Sapthagiri main road near jym opp |
| 03. Purpose of Ground Water | Drinking water |
| 04. Area | Shettyhalli |
| 05. Approximate Drilling Depth | 350-370 rmt |
| 06. Approximate Casing Pipe | 30-50 rmt |
| 07. PVC Pipe | 10-15 rmt |
| 08. Expected Yield | 1500-2000 GPH |
| 10. Remarks | |

*Note:* Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

RAJALAKSHMI GEO CONSULTANTS
GEOLOGIST

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ.12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು